


CORNER RECORD

Agency Index BK 23, PG 37Document Number 20200081City of Rocklin County of Placer, CaliforniaBrief Legal Description Centerline Antelope Ct., Antelope Oaks Unit No. 1, Bk. L of Maps, Pg. 86

Se 18

**CORNER TYPE**

- ☐ Government Corner ☒ Control
☐ Meander ☐ Property
☐ Rancho ☐ Other

Date of Survey October 16, 2020**COORDINATES (Optional)**

N. _____ E. _____

Elevation _____

Units ☐ Metric ☐ U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

T. 11 N., R. 7 E., M.D.B. & M.

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:Corner/Monument: ☒ Left as found ☐ Established ☐ Rebuilt ☒ Pre-Construction☐ Found and tagged ☐ Reestablished ☒ Referenced ☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

Found railroad spike with punch at the centerline of Antelope Court, Antelope Oaks Unit No. 1, as shown on Bk. L of Maps, Pg. 86 that could be damaged or destroyed by a proposed paving project. Monument was referenced as shown on page 2 of 2. The purpose of this Corner Record is to preserve the location of the monument prior to construction. No attempt was made to determine the relationship between the monument and boundary lines.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on January 14, 2021Signed [Signature] P.L.S. or R.C.E. No. PLS. 5914**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received JANUARY 26, 2021and examined and filed JANUARY 29, 2021Signed [Signature] P.L.S. or R.C.E. No. 8373Title Deputy Co. Surveyor

County Surveyor's Comment



BOOK 23 OF CORNER RECORDS PAGE 37



SCALE: 1" = 40'

